





40T S4 H50 Ø42 Clamp Bending



Part number 1: Main V Die for All Clamps
Part number 5: Gas Spring Holder
Part number 4: Special Punch for s4 Ø42 H50 Clamp
Part number 6: Ø42 Punch